

AIRPOWER®

P7 MID


Art. No. 206214



HAIX® Secura Liner®, HAIX® Sun Reflect Leather, HAIX® Climate System, HAIX® AS System, Leg height: 6 inches, sole 014

Available sizes: 4 ½ – 15 & half sizes

Available widths: Medium, Wide



HAIX® AS System



206214

HAIX® Secura Liner®

Footwear inner liner which will never pull out or wrinkle up over time; lining is firmly secured and sealed along with the upper leather beneath the sole.

HAIX® Sun Reflect Leather

Reduces the heating effect of the upper leather by direct sunlight. Sunlight is reflected by the leather, keeping the leather and the feet cooler.

HAIX® Climate System

Permits air circulation with every step – moist air is released and fresh air comes in through the vent holes at the top of the boot.

HAIX® AS System

Supports the arch of the foot in its natural, ideal position

Upper Material

Soft and supple waterproof leather, hydrophobic, breathable.

Moisture Barrier

CROSSTECH® Laminat Technology; Watertight and breathable. Abrasion-resistant lining with optimized climate comfort for all seasons, espec.

Sole

Rubber compound outsole with PU wedge which is fuel-oil and skid resistant, with a non-marking, self-cleaning, antistatic tread. Excellent insulation against heat and cold.

Insole

Anatomically formed, quick change, machine washable insert with excellent moisture absorption and quick drying qualities.

Footbed

Anatomically formed TEXON (fleece) absorbs moisture and supports ankle.

Other

Anatomically formed and softly padded tongue, lightweight, high quality quick lacing eyelets, highly breathable nylon fabric, and reinforcement in the toe and heel area.

Extended Wear Program

Out of warranty footwear can be refurbished with original factory parts through an extended wear package. This package includes any necessary replacement or repair of stitching, profiled rubber toe caps, insoles, and retreading of soles. Footwear will be cleaned and deodorized. HAIX footwear owners also have the option of a sole retread only or a toe cap replacement only.

| | | | | | | | | | | | | | | | | | | | | | | | | | |
|----|----|----|----|----|----|----|----|----|----|----|----|----|----|-----|----|-----|----|-----|----|-----|----|-----|----|-----|----|
| UK | 3 | 3½ | 4 | 4½ | 5 | 5½ | 6 | 6½ | 7 | 7½ | 8 | 8½ | 9 | 9½ | 10 | 10½ | 11 | 11½ | 12 | 12½ | 13 | 13½ | 14 | 14½ | 15 |
| EU | 35 | 36 | 37 | 37 | 38 | 39 | 39 | 40 | 41 | 41 | 42 | 43 | 43 | 44 | 45 | 45 | 46 | 47 | 47 | 48 | 48 | 49 | 50 | 50 | 51 |
| US | 4 | 4½ | 5 | 5½ | 6 | 6½ | 7 | 7½ | 8 | 8½ | 9 | 9½ | 10 | 10½ | 11 | 11½ | 12 | 12½ | 13 | 13½ | 14 | 14½ | 15 | 15½ | 16 |

HAIX® North America INC.

2320 Fortune Drive, Suite 120, Lexington, KY 40509
 Phone 859-281-0111, Fax 859-281-0113
 Toll free 866-344-HAIX (4249), www.haix.com