

AIRPOWER® XR200

Art. No. 604103 men, 604104 women



ASTM F2413-2011, CAN/CSA Z195-2014

HAIX® Secura Liner, HAIX® Climate System, HAIX® FP System, HAIX® AS System, HAIX® Composite Toe Cap, HAIX® 2-Zone Lacing, Leg height: 7 inches
Available sizes: Men 4 ½ – 14 ½ & half sizes, Women 5 – 12 & half sizes



HAIX® AS System



HAIX® Secura Liner®

Footwear inner liner which will never pull out or wrinkle up over time; lining is firmly secured and sealed along with the upper leather beneath the sole.

HAIX® Climate System

Permits air circulation with every step – moist air is released and fresh air comes in through the vent holes at the top of the boot.

HAIX® FP System

Flex Protection System: Leather reinforcement over the heel bend which protects this softer and more flexible leather from chafing.

HAIX® AS System

Supports the arch of the foot in its natural, ideal position

HAIX® Composite Toe Cap

Anatomically formed, ultra-lightweight protective toe cap made of fiber-reinforced composite for highest safety requirements.

Cut Protection

Para-aramid cut protection.

Protective Throughsole

Puncture resistant, non-metallic, to meet ASTM F2413-11 and CAN/CSA Z195-2014 standard for personal protection – protective footwear

Upper Material

Oiled nubuk leather, waterproof, hydrophobic, and breathable.

Moisture Barrier

GORE-TEX® footwear, 4 layers with inner Cambrelle lining, abrasion resistant, softly padded with functional non-woven fabric. Waterproof, breathable, and chemical resistant.

Sole

Extremely slip resistant rubber sole with PU wedge which is fuel, oil, and skid resistant, with a non-marking, self-cleaning tread. Excellent insulation against heat and cold. Sole is heat resistant and electrical insulating.

Footbed

Anatomically formed, quick change, machine washable insert with excellent moisture absorption and quick drying qualities.

Insole

Non-woven insole absorbs sweat and moisture.

HAIX® 2-Zone Lacing

Two Zone Lacing System enables a separate adjustment of the boot to the foot and leg area.

Other

Integrated heel bend, TPU toe cap, no side seams and reinforcement in the toe area.

Extended Wear Program:

Out of warranty footwear can be refurbished with original factory parts through an extended wear package. This package includes any necessary replacement or repair of stitching, profiled rubber toe caps, insoles, and retreading of soles. Footwear will be cleaned and deodorized. HAIX footwear owners also have the option of a sole retread only or a toe cap replacement only.

| | | | | | | | | | | | | | | | | | | | | | | | | | |
|----|----|----|----|----|----|----|----|----|----|----|----|----|----|-----|----|-----|----|-----|----|-----|----|-----|----|-----|----|
| UK | 3 | 3½ | 4 | 4½ | 5 | 5½ | 6 | 6½ | 7 | 7½ | 8 | 8½ | 9 | 9½ | 10 | 10½ | 11 | 11½ | 12 | 12½ | 13 | 13½ | 14 | 14½ | 15 |
| EU | 35 | 36 | 37 | 37 | 38 | 39 | 39 | 40 | 41 | 41 | 42 | 43 | 43 | 44 | 45 | 45 | 46 | 47 | 47 | 48 | 48 | 49 | 50 | 50 | 51 |
| US | 4 | 4½ | 5 | 5½ | 6 | 6½ | 7 | 7½ | 8 | 8½ | 9 | 9½ | 10 | 10½ | 11 | 11½ | 12 | 12½ | 13 | 13½ | 14 | 14½ | 15 | 15½ | 16 |

HAIX® North America INC.

2320 Fortune Drive, Suite 120, Lexington, KY 40509

Phone 859-281-0111, Fax 859-281-0113

Toll free 866-344-HAIX (4249), www.haix.com